



15 May 2008

Mapping & GIS: Current Software Versions

This document gives the current software versions of Trimble® Mapping & GIS products. For details on upgrades and downloads, refer to the support area for each product on the Trimble website (www.trimble.com/support).

* Indicates discontinued product

	Platform	Current version
Field software		
ASPEN® software*	Windows®	2.11
Asset Surveyor® software*	TDC1™ / TDC2™	3.40
	TSC1™	5.27
GeoBeacon™ Controller software	Windows, Windows CE	1.0.32
GeoExplorer® I and II handhelds*		2.20
GeoExplorer 3 and 3c handhelds*		1.20
GPS Controller software	Windows, Windows CE	2.15
	GeoExplorer 2008 series	2.20
GPS Pathfinder® Controller software*	Palm OS	1.20
	Windows, Windows CE	1.31
Trimble GPScorrect™ extension for ESRI ArcPad software	Windows, Windows CE	2.41
GPS Pathfinder Tools Software Development Kit (SDK)	Windows, Windows CE	2.31
TerraSync™ software	Windows, Windows CE	3.21
TrimPix™ technology	Windows Mobile® 5.0, 6	1.10
Office software		
Data Transfer Utility	Windows	1.43
GPS Pathfinder Office software	Windows	4.10
Trimble GPS Analyst™ extension for ESRI ArcGIS software	Windows	2.10
MediaMapper software*	Windows	3.1–20
Trimble Reference Station (TRS™)*	Windows	1.05

This document is for informational purposes only and is not a legally binding agreement or offer. Trimble makes no warranties and assumes no obligations or liabilities hereunder.

Trimble Navigation Limited, 10355 Westmoor Drive, Suite #100, Westminster, CO 80021, USA

© 2006–2008, Trimble Navigation Limited. All rights reserved. Trimble, the Globe & Triangle logo, ASPEN, Asset Surveyor, GeoExplorer, and GPS Pathfinder are trademarks of Trimble Navigation Limited registered in the United States and other countries. BoB, GeoBeacon, GPS Analyst, GPScorrect, Juno, ProXH, ProXRT, ProXT, TDC1, TDC2, TerraSync, TrimPix, TRS, TSC1, and TSCe are trademarks of Trimble Navigation Limited. Recon, Nomad, and Ranger are either registered trademarks or trademarks of Tripod Data Systems Inc. Microsoft, Windows, and Windows Mobile are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries. All other trademarks are the property of their respective owners.



	Embedded software	Current version
Hardware		
BoB™ (Beacon-on-a-Belt) receiver*		1.00
GeoBeacon Receiver		1.35, 1.30
Juno™ ST handheld	Operating system revision	Windows Mobile version 5.0 software
	GPS firmware	3.10
GeoExplorer 2008 series handhelds	Operating system revision	Windows Mobile 5.0 software; revision 5.2.5
	GPS firmware	2.01
GeoExplorer 2005 series handhelds	Operating system revision	Windows Mobile 5.0 software; revision 5.1.16
	GPS firmware	1.82
GeoExplorer 2003 series handhelds*	Operating system revision	Windows Mobile 2003 software for Pocket PCs; revision 3.00.03
	GPS firmware	1.05A
GeoExplorer CE series handhelds*	Operating system revision	Windows CE .NET; revision 2.00.02 Windows CE version 3.0; revision 1.10.02
	GPS firmware	1.05A
GPS Pathfinder Pocket receiver*		1.00
GPS Pathfinder XB receiver		2.30
GPS Pathfinder XC receiver		3.10
GPS Pathfinder Power receiver*		1.70
GPS Pathfinder ProXH™ receiver		1.82
GPS Pathfinder Pro XL receiver*		3.15
GPS Pathfinder Pro XR receiver*		1.96, 1.31
GPS Pathfinder Pro XRS receiver*		1.96, 1.52A
GPS Pathfinder ProXT™ receiver		1.82
GPS Pathfinder ProXRT™ receiver		3.60
GIS TSCe™ field device*	Operating system revision	Windows CE .NET version 4.0.11 Windows CE version 3.0 (Build 126); revision 2.3.7
Trimble Nomad™ series handhelds	Operating system revision	Windows Mobile version 6 operating system; revision 5.2
	GPS firmware	3.10

	Embedded software	Current version
Trimble Ranger™ handheld	Operating system revision	Windows Mobile 5.0 software; revision 5.0.3 Windows Mobile 2003 Software for Pocket PCs version 4.2.2C*
Trimble Recon® handheld	Operating system revision	Windows Mobile 6 operating system; revision 6.0.1 Windows Mobile 5.0 software; revision 5.0.2* Windows Mobile 2003 Software for Pocket PCs version 4.2.5* Windows CE .NET version 4.1.9*